

SF61B

Accessory Guide

Wearables

| Accessory Name | Part Number | Description | Backward Compatible with SF51 |
|------------------------------|---------------|--|-------------------------------|
| Magnet End-Cap and Belt Loop | SF61-MAG-S001 | This two-piece kit secures the scanner to your belt with magnetic force. Simply attach the belt loop with magnet to your belt, and affix the magnetic end-cap to the SF61B mobility scanner. This provides a quick and convenient attach/release method. A small plastic tool is included for installation/removal. | No |
| Ring End-Cap and Wrist Strap | SF61-RIN-S001 | This two-piece kit includes a end-cap with ring that affixes to the SF61B mobility scanner, and a convenient wrist strap with cord-tightener. Simply thread the wrist strap through the ring, and the scanner can be conveniently worn around your wrist or arm--yet easily stowed away when both hands are needed. A small plastic tool is included for installation/removal. | No |
| Belt Loop, Standard | 825-171-002 | Belt loop with snap closure, allowing the SF61B to be conveniently attached to your belt. Note: Does not include the scanner magnet end-cap (see SF61-MAG-S001 for the entire kit). | Yes |
| Belt Clip, Industrial | 825-172-002 | A more heavy-duty version of the above belt loop, this industrial clip allows the SF61B to be conveniently attached to your belt. Note: Does not include the scanner magnet end-cap (see SF61-MAG-S001). | Yes |
| Chest Strap Holder | 825-173-002 | Designed for high-volume scanning in the DC or warehouse, this chest strap includes an adjustable waist with heavy-duty side squeeze buckle, and suspender with magnetic attachment. Fully adjustable. | Yes |

SF61B

Accessory Guide



Holders and Chargers

| Accessory Name | Part Number | Description | Backward Compatible with SF51 |
|---|---------------|---|-------------------------------|
| USB Charger, Single Bay  | SF61-UPK-S001 | Charge a single SF61B mobility scanner via a USB port. (Requires a minimum 5V power source.) | No |
| Charge Cradle, Single Bay  | 871-221-001 | Charge cradle accommodates a single SF61B or SF51 mobility scanner. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-089-306) must be purchased separately. | Yes |
| Charge Cradle, Quad Bay  | 871-222-001 | Charge cradle accommodates up to four SF61B or SF51 mobility scanners. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-088-201) must be purchased separately. | Yes |
| FlexDock Cup, Dual Charge  | 213-007-001 | Supports the charging of two SF61B scanners when snapped into the bay of a FlexDock base (ordered separately--see below). | No |
| FlexDock Base, Quad Charge  | 852-916-001 | Provides four bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to eight SF61B mobility scanners. FlexDock cups, power supply (851-064-327), and country-specific line cord must be ordered separately. | No |
| FlexDock Base, Dual Charge  | 852-918-001 | Provides two bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to four SF61B mobility scanners. FlexDock cups, power supply (851-095-121), and country-specific line cord must be ordered separately. | No |
| FlexDock Kit, Quad Charge  | DX2A28820 | This comprehensive charge kit includes: two SF61B FlexDock cups, a FlexDock dual charge base, and a universal power supply. Must order country-specific line cord separately. | No |

SF61B

Accessory Guide

Holders and Chargers

| Accessory Name | Part Number | Description | Backward Compatible with SF51 |
|--|---------------|---|-------------------------------|
| AC Charger, Single Bay  | SF61-APK-S001 | Charge a single SF61B mobility scanner. Must order country-specific line cords separately. | No |
| Vehicle Power Adapter Kit  | SF61-VPK-S001 | Includes a scanner holder, cable and 12V DC power socket for connecting to your vehicle's power accessory (cigar lighter) port. Charges a single scanner. | No |

Cables and Accessories

| Accessory Name | Part Number | Description | Backward Compatible with SF51 |
|--|---------------|---|-------------------------------|
| Spare Battery  | SF61-BAT-S001 | To extend the long-term service life of the scanner, this 2,600 mAh spare battery can be installed in the field. | No |
| Universal Power Supply  | 851-089-306 | This 5V DC power supply provides scanner power for use when host device power alone is insufficient. Includes ferrite (level V). Must order country-specific line cords separately. | Yes |
| Universal Power Supply for Quad Bay Charger  | 851-088-201 | Power supply for use with the quad-bay charger only (part number 871-222-001). Must order country-specific line cords separately. | Yes |
| FlexDock Quad Base Power Supply  | 851-064-327 | A 100W power supply for use with the FlexDock Quad base. Requires country-specific line cord to be ordered separately. | Yes |
| FlexDock Dual Base Power Supply  | 851-095-121 | A 48W power supply for use with the FlexDock Dual base. Requires country-specific line cord to be ordered separately. | Yes |



www.L-TronDirect.com

800-830-9523

info@L-Tron.com

596 Fishers Station Dr | Victor, NY | 14564 | Suite 1 A

www.L-Tron.com

